

**Flood Control Project Maintenance
Levee Inspections**

2018 Channel Summary Report

Overall Unit and Item Ratings

Adin Community Service District

Ash Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Dry Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****Adin Community Service District**

Channel
Ash Creek

Channel Rating	A
Date of Inspection	6/12/2018
DWR Inspector	Bob Duffey
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_1			
Action/Comments				
Inspector Comments: The channel is clear of vegetation & obstructions.				

Photo 1 of 1 : CH_2018_NA0030_1_1_20180618_00007.jpg



View from Main Street (Highway 299) towards the gauging station.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Up (cont)

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_4			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

Check Point / View

Main Street / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_6			

Action/Comments

Inspector Comments: The channel is clear of vegetation & obstructions.

Photo 1 of 1 : CH_2018_NA0030_1_6_20180618_00008.jpg



View from Main Street (Highway 299) towards the Ash Street low water crossing.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c _ 2012_9			
Action/Comments				
Inspector Comments: Riprap clearly visible.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Down (cont)

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.197770 °
Category	Rivers, Channels & Designated Flood			-120.944100 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_10			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

Check Point / View

Ash Street / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_11			

Action/Comments

Inspector Comments: The channel is clear of vegetation & obstructions.

Photo 1 of 1 : CH_2018_NA0030_1_11_20180618_00009.jpg



View of the channel from Ash Street low water crossing.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_12			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Ash Street / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_13			

Action/Comments

Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_14			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged.

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_15			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Ash Street / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c _ 2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2018_NA0030_1_16_20180718_00013.jpg



Vegetation well maintained or not impacting capacity.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	M	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c _ 2012_18			
Action/Comments				
Inspector Comments: During low flows you can see the two gravel bars in channel and monitor erosion during high flows.				

Photo 1 of 1 : CH_2018_NA0030_1_18_20180618_00010.jpg



View of the gravel bars and moderate erosion on both banks.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Ash Street / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c_2012_19			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		41.197138 °
Category	Rivers, Channels & Designated Flood			-120.945271 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_20			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

Check Point / View

Downstream limit/fish ladder & walkway / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_31			

Action/Comments

Inspector Comments: The channel is clear of vegetation & obstructions.

Photo 1 of 1 : CH_2018_NA0030_1_31_20180618_00011.jpg



View of the upstream side of the weir.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Downstream limit/fish ladder & walkway / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c_2012_33			
Action/Comments				
Inspector Comments: There is minor erosion along both sides of the structure.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c _ 2012_34			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Downstream limit/fish ladder & walkway / Up (cont)

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c_2012_35			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

Check Point / View

Downstream limit/fish ladder & walkway / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_1_c_2012_36			

Action/Comments

Inspector Comments: The channel is clear of vegetation & obstructions.

Photo 1 of 1 : CH_2018_NA0030_1_36_20180618_00012.jpg



View of the downstream side of the weir.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_1_c_2012_37			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Ash Creek	1.00	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Downstream limit/fish ladder & walkway / Down (cont)

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_1_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.				

No Photos

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Revetments			
DWR ID	DWR_NA0030_1_c _ 2012_39			
Action/Comments				
Inspector Comments: Place more riprap on both sides of weir to prevent erosion.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		41.192990 °
Category	Rivers, Channels & Designated Flood			-120.954530 °
Item	Encroachments			
DWR ID	DWR_NA0030_1_c _ 2012_40			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****Adin Community Service District**

Channel
Dry Creek

Channel Rating	A
Date of Inspection	6/12/2018
DWR Inspector	Bob Duffey
Accompanied By	Mike Williams Adin Community Service District

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Adin Street / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c _ 2012_1			
Action/Comments				
Inspector Comments: Remove all vegetation in channel before winter. Mike Williamson said they will remove the vegetation before winter.				

Photo 1 of 1 : CH_2018_NA0030_2_1_20180618_00005.jpg



View from Adin Street looking upstream at minimal vegetation in channel.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_2_c_2012_3			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Adin Street / Up (cont)

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Revetments			
DWR ID	DWR_NA0030_2_c_2012_4			

Action/Comments

Inspector Comments: No revetments were observed.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

Check Point / View

Adin Street / Down

Rating **	M	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_6			

Action/Comments

Inspector Comments: Remove all vegetation in channel before winter.

Photo 1 of 1 : CH_2018_NA0030_2_6_20180618_00006.jpg



View from Ash Street looking downstream at minimal vegetation in channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Adin Street / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_2_c _ 2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Revetments			
DWR ID	DWR_NA0030_2_c_2012_9			
Action/Comments				
Inspector Comments: No revetments were observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Adin Street / Down (cont)

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		41.195370 °
Category	Rivers, Channels & Designated Flood			-120.943190 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

Check Point / View

Main Street / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_11			
Action/Comments				
Inspector Comments: Remove all vegetation in channel before winter.				

Photo 1 of 1 : CH_2018_NA0030_2_11_20180618_00007.jpg



View from Main Street looking upstream at minimal vegetation in channel.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c _ 2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_2_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Revetments			
DWR ID	DWR_NA0030_2_c _ 2012_14			
Action/Comments				
Inspector Comments: No revetments were observed.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash, debris or other obstructions present within the easement.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District


Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0030_2_c_2012_16			
Action/Comments				
Inspector Comments: Remove all vegetation in channel before winter. The grass should be mowed before flood season.				

Photo 1 of 1 : CH_2018_NA0030_2_16_20180618_00008.jpg



View from Main Street looking downstream at minimal vegetation in channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0030_2_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0030_2_c_2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Adin Community Service District

Channel	Channel Length	Inspection Start/End	Inspector
Dry Creek	0.20	06/12/2018 06/12/2018	Bob Duffey

Check Point / View

Main Street / Down (cont)

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Revetments			
DWR ID	DWR_NA0030_2_c_2012_19			

Action/Comments

Inspector Comments: No revetments were observed.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		41.196350 °
Category	Rivers, Channels & Designated Flood			-120.944250 °
Item	Encroachments			
DWR ID	DWR_NA0030_2_c_2012_20			

Action/Comments

Inspector Comments: No trash, debris or other obstructions present within the easement.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement